


UNIVERSAL MAP SENSOR 4 BAR MAP-067




CALIBRATION

20kpa = 0.200v
400kpa = 4.800v

WIRING DETAILS

PIN	Description
1	GND
2	Signal OUT
3	+5 Vdc


CONNECTOR KIT



Use tool RWT-005 to crimp the pins.



Part No. MAP-067



Harness Side View

