


UNIVERSAL MAP SENSOR 4 BAR MAP-067



CALIBRATION

20kpa Absolute = 0.200v
400kpa Absolute = 4.800v


WIRING DETAILS

PIN	Description
1	GND
2	Signal OUT
3	+5 Vdc




Part No. MAP-067

CONNECTOR KIT



Use tool RWT-005 to crimp the pins.



Harness Side View

